DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.9/14.3,0.0/1.6

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000820 Address: 333 Burma Road **Date Inspected:** 07-Nov-2007

City: Oakland, CA 94607

OSM Arrival Time: 600 **Project Name:** SAS Superstructure **OSM Departure Time:** 1530 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Contractor: Location:** Shanghai, China

CWI Name: CWI Present: Yes Ye Yong Jun, Li Gang No **Inspected CWI report:** Yes **Rod Oven in Use:** Yes No No N/A N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** CalTrans mock up

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Dan Hernandez was present to observe the fitup, welding and related activities associated with the fabricating of Caltrans Mock-ups 89.00 and 77.00 for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island. **Item Description**

77M Flange Reinforcing Ring

MT at weld run off tabs of

Caltrans QA Inspector observed ZPMC QC Zhon Dong Yun perfrom Magnetic Particle (MT)Inspection on the areas where the weld run off tabs were removed from flange reinforcing ring SA273. Inspected area appeared to be free of discontinuities.



WELDING INSPECTION REPORT

(Continued Page 2 of 2)

89M Diaphragm

MT of tack welds in prog

Caltrans QA Inspector observed ZMPC QC Zhon Dong Yun perform Magnetic particle (MT) inspection on tack welds of diaphragm web plates to diaphragm SA13-1. Inspected area appeared to be free of discontinuities.



Summary of Conversations:

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer